∩**ጸ**_1

Ph. 26X1A

NPIC/P&DS/D/6-1426 17 June 1966

25X1A	SUBJECT: 70mm Data Blo	ock Reader	·
25X1A 25X1A	order data. EPS attempted repair	on 6-3-66. on until 6-8-66, when it began to miss low, but procedures used, including suggestice problem. The nature of the trouble	w ons
25X1A 25X1A	The conclusion reached by	14-66 to determine the cause of the malfur was that the metering system drive roll resultant measuring error caused data to	nction ler
25X1A	3. A temporary repair was meroller diameter. will the fabrication and installation	ade utilizing plastic tape to increase the request additional contract funds to cover of a new roller.	e r
:		25X1A	
		Equipment Pertormance Section DB/F	28.DG

Declass Review by NIMA/DOD